DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006193 Address: 333 Burma Road **Date Inspected:** 08-Apr-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Location: Shanghai, China

CWI Name: Li Yan Hua **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG Assembly

Summary of Items Observed:

On this date CALTRANS OSM Quality Assurance (QA) Inspector was present during the times noted above for observations relative to the work being performed.

Segment Repair Yard (South of Bay 13)

Segment 2BW

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the deck panel weld splices. The Weld Designations are as follows: SEG009*-004, 005, 021 and 022.

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the deck panel diaphragm weld splices. The Weld Designations are as follows: SEG009*-009, 010, 011, 012 and 024.

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the side and bottom panel weld splices. The Weld Designations are as follows: SEG009A-007, 008 and 010.

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the floor beam component welds. The Weld Designations are as follows:

SSD14-PP17-202

SSD14A-PP17-198

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the lifting lugs. The Weld Designations are as follows:

SSD14-PP17-220 and 234.

SSD14A-PP17-220 and 234.

Segment Splice Yard (North of bay 12)

Crossbeam 2

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the floor beam component welds. The Weld Designations are as follows: FB210-001-037 and 038.

FB210-1-001-037 and 038.

This QA Inspector performed Ultrasonic testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated a (UT) report for this date. The members are identified as the side panel rib stiffener splices. The Weld Designations are as follows: SP217-031~036.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, (15000422372), who represents the Office of Structural Materials for your project.

| Inspected By: | Patterson, Rodney | Quality Assurance Inspector |
|----------------------|-------------------|-----------------------------|
| Reviewed By: | Carreon, Albert | QA Reviewer |